



Advanced Inspection Report (22-Aug-2024 03:08 PM)

## Bmw 5-SERIES

### IMAGES



## CAR DETAILS

Make	<b>Bmw</b>	Model	<b>5-SERIES</b>
Year	<b>2016</b>	KMS Driven	<b>72000</b>
Spec	<b>Gcc</b>	Trim	<b>520i</b>
Engine Size	<b>2.0L</b>	No. of Cylinders	<b>4</b>
Fuel Type	<b>Petrol</b>	Transmission	<b>Automatic</b>
Body Type	<b>Sedan</b>	Exterior Color	<b>BLUE</b>
Interior Color	<b>BEIGE</b>	Wheel Type	<b>2WD</b>
Service History	<b>Partly Available</b>	Warranty	<b>Out of Warranty</b>
Service Contract	<b>Not Available</b>	Owner	<b>2nd</b>
Spare Keys	<b>1</b>	Accident	<b>No</b>
Registered Emirates	<b>Dubai</b>		

## CAR FEATURES

AC	<b>Yes</b>	Backup Camera	<b>Yes</b>
Cruise Control	<b>Yes</b>	Navigation	<b>No</b>
Power Locks	<b>Yes</b>	Power Seats	<b>Yes</b>
Heated Seats	<b>No</b>	Airbag: Driver	<b>Yes</b>
Airbag: Passenger	<b>Yes</b>	Antilock Brakes	<b>Yes</b>
Fog Lights	<b>Yes</b>	Security System	<b>Yes</b>
Power Windows	<b>Yes</b>	Windows Defroster	<b>Yes</b>
Tinted Glass	<b>Yes</b>	Stereo Music System	<b>No</b>
Touch Screen Infotainment System	<b>Yes</b>	Alloy Wheels	<b>Yes</b>
Keyless Entry	<b>Yes</b>	Sunroof	<b>Yes</b>

## CAR ANALYSIS

Radiator Condition	<b>Good</b>	Radiator Fan	<b>Good</b>
Engine Noise	<b>Good</b>	Axels	<b>Good</b>
Coolant	<b>Good</b>	Engine Idling	<b>Good</b>
Engine Smoke	<b>Good</b>	Transmission Condition	<b>Good</b>
Silencer	<b>Good</b>	Airbag	<b>Good</b>
Chassis	<b>Good</b>	Chassis Extension	<b>Good</b>
Warning Signal	<b>Good</b>	Oil Leaks	<b>Good</b>
Shift Interlock Condition	<b>Good</b>	Engine Group	<b>Good</b>
Hoses And Pipes Condition	<b>Good</b>	Brake Pads	<b>Good</b>
Brake Discs Or Lining	<b>Good</b>	Parking Brake Operations	<b>Good</b>
Suspension	<b>Good</b>	Shock Absorber Operation	<b>Good</b>
Steering Operation	<b>Good</b>	Steering Alignment	<b>Good</b>
Wheel Alignment	<b>Good</b>	Rotors And Drums	<b>Good</b>
Struts And Shocks	<b>Good</b>	Dashboard Condition	<b>Good</b>
Steering Mounted Controls	<b>Good</b>	Center Console Box	<b>Good</b>
Speedometer Cluster	<b>Good</b>	Door Trim Panels	<b>Good</b>
Headliner	<b>Good</b>	Seat Controls	<b>Good</b>
Boot Trunk Area	<b>Good</b>	Central Lock Operation	<b>Good</b>
Music Multimedia System	<b>Good</b>	Navigation Control	<b>Good</b>
Headlights	<b>Good</b>	Tail Lights	<b>Good</b>
Sunroof Condition	<b>Good</b>	Windows Controls Condition	<b>Good</b>
Cruise Control	<b>Good</b>	Push Stop Button	<b>Good</b>
Ac Cooling	<b>Good</b>	Convertible Operations	<b>Good</b>
Ac Heating	<b>Good</b>		

---

## CAR EXTERIOR

---

### Description

2016  
BMW 520i  
2.0L 4 Cylinders  
184 BHP

-----  
GCC specifications  
72,000 kms  
Full service history!  
-----

1. Midnight Blue with beige Leather Interior
2. Bluetooth System?
3. Climate Control
4. Cruise Control?
5. Rear View Camera??
6. Power Sunroof??
7. Keyless Entry and Start?
8. AutoHold ?
9. Power Seats
10. Park Assist
11. Front and Rear Parking Sensors
12. Dual Exhaust System
13. Fog Lights

AND MUCH MUCH MORE ...