



Advanced Inspection Report (06-Feb-2026 01:02 PM)

Honda CR-V

IMAGES







CAR DETAILS

Make	Honda	Model	CR-V
Year	2017	KMS Driven	102000
Spec	Gcc	Trim	Lx
Engine Size	2.4L	No. of Cylinders	4
Fuel Type	Petrol	Transmission	Automatic
Body Type	SUV	Exterior Color	White

Interior Color	Beige	Wheel Type	2WD
Service History	Not Available	Warranty	Out of Warranty
Service Contract	Not Available	Owner	1st
Spare Keys	1	Accident	No
Registered Emirates	Dubai		

CAR FEATURES

AC	Yes	Backup Camera	No
Cruise Control	Yes	Navigation	Yes
Power Locks	Yes	Power Seats	No
Ventilated Heated Seats	No	Ventilated Cold Seats	No
Airbag: Driver	No	Airbag: Passenger	Yes
Antilock Brakes	Yes	Fog Lights	Yes
Security System	No	Power Windows	Yes
Windows Defroster	No	Tinted Glass	No
Stereo Music System	Yes	Touch Screen Infotainment System	No
Alloy Wheels	No	Keyless Entry	Yes
Sunroof	No	360 Camera	No
Apple Car Play	No	Panoramic Glass Roof	No
Blind Spot Monitor	No	Lane Keep Assist	No
Collision Warning System	No	LED Headlights	No
Brake Assist	No	Bluetooth	Yes
Premium Sound System	No	Rear Entertainment Screens	No
Leather Seats	No	Push Start	No
Remote Start	No	Ambient Lighting	No
Headsup Display	No	Parking Sensors	Yes
Memory Seats	No	Power Folding Mirrors	No

Reversing Camera	No	Birds Eye View Camera	No
Adaptive Cruise Control	No	Digital Display	No
Soft Close Door	No	Hands Free Liftgate	No
Massage Seats	No	Steering Wheel Control	No
Paddle Shifters	No	Auto Dimming Mirror	No
Digital Display Mirror	No	Lumbar Support	No
Electric Running Board	No	Automated Parking	No

CAR ANALYSIS

Radiator Condition	Good	Radiator Fan	Good
Engine Noise	Good	Axels	Good
Coolant	Good	Engine Idling	Good
Engine Smoke	Good	Transmission Condition	Good
Silencer	Average	Airbag	Good
Chassis	Good	Chassis Extension	Good
Warning Signal	Good	Oil Leaks	Good
Shift Interlock Condition	Good	Engine Group	Good
Hoses And Pipes Condition	Good	Brake Pads	Average
Brake Discs Or Lining	Average	Parking Brake Operations	Good
Suspension	Good	Shock Absorber Operation	Average
Steering Operation	Good	Steering Alignment	Average
Wheel Alignment	Average	Rotors And Drums	Average
Struts And Shocks	Good	Dashboard Condition	Good
Steering Mounted Controls	Good	Center Console Box	Good
Speedometer Cluster	Good	Door Trim Panels	Good
Headliner	Good	Seat Controls	Average

Boot Trunk Area	Good	Central Lock Operation	Good
Music Multimedia System	Good	Navigation Control	Good
Headlights	Good	Tail Lights	Good
Sunroof Condition	Good	Windows Controls Condition	Good
Cruise Control	Good	Push Stop Button	Good
Ac Cooling	Good	Convertible Operations	Good
Ac Heating	Good	Engine Mountings	Average
Gear Mounting	Good	Differential Mounting	Good
Propeller Shaft	Good	Differential And Transfer Case	Good
Tires Condition	Average	Horn	Average
Interior Noise	Normal	4X4 Operation	Good

CAR EXTERIOR

Front Right Doors

Original : "

Front Left Doors

Original : "

Rear Right Doors

Portion Repainted : "

Rear Left Doors

Original : "

Bonnet

Portion Repainted : "

Back Bumper

Portion Repainted : "

Right Back Bumper

Original : "

Left Back Bumper

Portion Repainted : "

Right Front Panel

Original : "

Description

2017 GCC HONDA CRV LX 2WD // 2.4L 4CYL //
ASSURED VEHICLE!!

LIGHTS

-PASSED

BODY

-THERE IS COATING UNDER THE CAR

CHASIS

-CHASIS UNDERBODY COATING

PAINT

-PARTIAL PAINT ON SOME SPOTS

ROOF

-THERE IS A DENT ON A ROOF

BONNET AND TRUNK

-THERE IS SOME DENTS ON FRONT BUMPER

-PARTIAL PAINT ON BONNET &TRUNK

FENDERS

-PASSED

BUMPERS

-BACK BUBPER PARTIAL PAINT

RIMS

-PASSED

ENGINE

-PASSED

GEARBOX

-PASSED

ALIGNMENT

-STEERING ROD MIGHT NEED ALIGNMENT

TIRES & BRAKES

-PASSED

EXHAUST

-PASSED

HISTORY:

- ONE OWNER**
- 2 OEM KEYS**
- SERVICE HISTORY CONFIRMED**

TERMS & CONDITIONS: This certificate shows the test values at the time of inspection only, Price Of Car is not responsible for any hidden or future defects as inspection was done according to Price Of Car standards.