




Advanced Inspection Report (09-Mar-2026 02:03 PM)

Toyota LAND CRUISER

IMAGES







CAR DETAILS

Make	Toyota	Model	LAND CRUISER
Year	2008	KMS Driven	273000
Spec	Gcc	Trim	Gxr
Engine Size	4.0L	No. of Cylinders	6
Fuel Type	Petrol	Transmission	Automatic
Body Type	SUV	Exterior Color	RED

Interior Color	BEIGE	Wheel Type	4WD
Service History	Partly Available	Warranty	Out of Warranty
Service Contract	Partly Available	Owner	1st
Spare Keys	2	Accident	No
Registered Emirates	Dubai		

CAR FEATURES

AC	Yes	Backup Camera	No
Cruise Control	Yes	Navigation	No
Power Locks	Yes	Power Seats	No
Ventilated Heated Seats	No	Ventilated Cold Seats	No
Airbag: Driver	Yes	Airbag: Passenger	No
Antilock Brakes	Yes	Fog Lights	Yes
Security System	No	Power Windows	Yes
Windows Defroster	No	Tinted Glass	No
Stereo Music System	No	Touch Screen Infotainment System	No
Alloy Wheels	No	Keyless Entry	Yes
Sunroof	Yes	360 Camera	No
Apple Car Play	No	Panoramic Glass Roof	Yes
Blind Spot Monitor	No	Lane Keep Assist	No
Collision Warning System	No	LED Headlights	No
Brake Assist	No	Bluetooth	Yes
Premium Sound System	No	Rear Entertainment Screens	No
Leather Seats	Yes	Push Start	No
Remote Start	No	Ambient Lighting	No
Headsup Display	No	Parking Sensors	Yes
Memory Seats	No	Power Folding Mirrors	No

Reversing Camera	No	Birds Eye View Camera	No
Adaptive Cruise Control	No	Digital Display	No
Soft Close Door	No	Hands Free Liftgate	No
Massage Seats	No	Steering Wheel Control	No
Paddle Shifters	No	Auto Dimming Mirror	No
Digital Display Mirror	No	Lumbar Support	No
Electric Running Board	No	Automated Parking	No

CAR ANALYSIS

Radiator Condition	Good	Radiator Fan	Good
Engine Noise	Good	Axels	Good
Coolant	Good	Engine Idling	Good
Engine Smoke	Good	Transmission Condition	Good
Silencer	Good	Airbag	Good
Chassis	Good	Chassis Extension	Good
Warning Signal	Good	Oil Leaks	Good
Shift Interlock Condition	Good	Engine Group	Good
Hoses And Pipes Condition	Good	Brake Pads	Normal
Brake Discs Or Lining	Normal	Parking Brake Operations	Good
Suspension	Average	Shock Absorber Operation	Average
Steering Operation	Good	Steering Alignment	Average
Wheel Alignment	Average	Rotors And Drums	Average
Struts And Shocks	Average	Dashboard Condition	Normal
Steering Mounted Controls	Good	Center Console Box	Normal
Speedometer Cluster	Good	Door Trim Panels	Normal
Headliner	Good	Seat Controls	Normal

Boot Trunk Area	Normal	Central Lock Operation	Good
Music Multimedia System	Good	Navigation Control	Good
Headlights	Good	Tail Lights	Good
Sunroof Condition	Average	Windows Controls Condition	Normal
Cruise Control	Good	Push Stop Button	Good
Ac Cooling	Good	Convertible Operations	Good
Ac Heating	Good	Engine Mountings	Average
Gear Mounting	Good	Differential Mounting	Good
Propeller Shaft	Normal	Differential And Transfer Case	Good
Tires Condition	Normal	Horn	Normal
Interior Noise	Normal	4X4 Operation	Good

CAR EXTERIOR

Bonnet

Original : "

Back Bumper

Portion Repainted : "

Right Back Bumper

Original : "

Left Back Bumper

Original : "

Right Front Panel

Portion Repainted : "

Left Front Panel

Original : "

Right Back Panel

Original : "

Left Back Panel

Original : "

Description

GCC 2008 LAND CRUISER 4.0L V6

LIGHTS

-PASSED

BODY

-THERE IS COATING UNDER THE CAR

CHASIS

-CHASIS UNDERBODY COATING

PAINT

-PARTIAL PAINT ON SOME SPOTS

ROOF

-THERE IS A DENT ON A ROOF

BONNET AND TRUNK

-THERE IS SOME DENTS ON FRONT BUMPER

-PARTIAL PAINT ON TRUNK

FENDERS

- PARTIAL PAINT ON THE RIGHT SIDE FENDER

BUMPERS

-BACK BUBPER PARTIAL PAINT

RIMS

-PASSED

ENGINE

-PASSED

GEARBOX

-PASSED

ALIGNMENT

-STEERING ROD MIGHT NEED ALIGNMENT

TIRES & BRAKES

-PASSED

EXHAUST

-PASSED

HISTORY:

- ONE OWNER
- 2 OEM KEYS
- SERVICE HISTORY CONFIRMED
- NO ACCIDENTS ON MOI SYSTEM

2008

Toyota Land Cruiser GXR

4.0L V6

240 BHP

GCC Specs

273,000 KMS

TERMS & CONDITIONS:

This certificate shows the test values at the time of inspection only, Price Of Car is not responsible for any hidden or future defects as inspection was done according to Price Of Car standards.