Advanced Inspection Report (19-May-2026 07:05 PM)

Kia TELLURIDE

IMAGES














PRICE OF CAR


PRICE OF CAR












Lo
Lo











CAR DETAILS

Make	**Kia**	Model	**TELLURIDE**
Year	**2020**	KMS Driven	**108000**
Spec	**Gcc**	Trim	**EX**
Engine Size	**3.8L**	No. of Cylinders	**6**
Fuel Type	**Petrol**	Transmission	**Automatic**
Body Type	**SUV**	Exterior Color	**WHITE**

Interior Color	**TAN**	Wheel Type	**4WD**
Service History	**Partly Available**	Warranty	**Can Be Added**
Service Contract	**Not Available**	Owner	**1st**
Spare Keys	**2**	Accident	**No**
Registered Emirates	**Dubai**		

CAR FEATURES

AC	**Yes**	Backup Camera	**No**
Cruise Control	**Yes**	Navigation	**Yes**
Power Locks	**Yes**	Power Seats	**No**
Ventilated Heated Seats	**No**	Ventilated Cold Seats	**No**
Airbag: Driver	**Yes**	Airbag: Passenger	**Yes**
Antilock Brakes	**Yes**	Fog Lights	**No**
Security System	**Yes**	Power Windows	**Yes**
Windows Defroster	**No**	Tinted Glass	**Yes**
Stereo Music System	**Yes**	Touch Screen Infotainment System	**No**
Alloy Wheels	**Yes**	Keyless Entry	**Yes**
Sunroof	**Yes**	360 Camera	**Yes**
Apple Car Play	**No**	Panoramic Glass Roof	**No**
Blind Spot Monitor	**No**	Lane Keep Assist	**No**
Collision Warning System	**No**	LED Headlights	**No**
Brake Assist	**No**	Bluetooth	**Yes**
Premium Sound System	**No**	Rear Entertainment Screens	**No**
Leather Seats	**Yes**	Push Start	**No**
Remote Start	**No**	Ambient Lighting	**No**
Headsup Display	**No**	Parking Sensors	**Yes**
Memory Seats	**No**	Power Folding Mirrors	**No**

Reversing Camera	**No**	Birds Eye View Camera	**No**
Adaptive Cruise Control	**No**	Digital Display	**No**
Soft Close Door	**No**	Hands Free Liftgate	**No**
Massage Seats	**No**	Steering Wheel Control	**No**
Paddle Shifters	**No**	Auto Dimming Mirror	**No**
Digital Display Mirror	**No**	Lumbor Support	**No**
Electric Running Board	**No**	Automated Parking	**No**

CAR ANALYSIS

Radiator Condition	**Good**	Radiator Fan	**Good**
Engine Noise	**Good**	Axels	**Good**
Coolant	**Good**	Engine Idling	**Good**
Engine Smoke	**Good**	Transmission Condition	**Good**
Silencer	**Good**	Airbag	**Good**
Chassis	**Good**	Chassis Extension	**Good**
Warning Signal	**Good**	Oil Leaks	**Good**
Shift Interlock Condition	**Good**	Engine Group	**Good**
Hoses And Pipes Condition	**Good**	Brake Pads	**Good**
Brake Discs Or Lining	**Good**	Parking Brake Operations	**Good**
Suspension	**Good**	Shock Absorber Operation	**Good**
Steering Operation	**Good**	Steering Alignment	**Good**
Wheel Alignment	**Good**	Rotors And Drums	**Good**
Struts And Shocks	**Good**	Dashboard Condition	**Good**
Steering Mounted Controls	**Good**	Center Console Box	**Good**
Speedometer Cluster	**Good**	Door Trim Panels	**Average**
Headliner	**Average**	Seat Controls	**Average**

Boot Trunk Area	**Average**	Central Lock Operation	**Good**
Music Multimedia System	**Good**	Navigation Control	**Good**
Headlights	**Average**	Tail Lights	**Good**
Sunroof Condition	**Good**	Windows Controls Condition	**Average**
Cruise Control	**Good**	Push Stop Button	**Good**
Ac Cooling	**Good**	Convertible Operations	**Good**
Ac Heating	**Good**	Engine Mountings	**Good**
Gear Mounting	**Good**	Differential Mounting	**Good**
Propeller Shaft	**Good**	Differential And Transfer Case	**Good**
Tires Condition	**Average**	Horn	**Average**
Interior Noice	**Average**	4X4 Operation	**Good**

CAR EXTERIOR

Front Right Doors
Original : ''

Front Left Doors
Original : ''

Rear Right Doors
Original : 'DENTS'

Rear Left Doors
Original : ''

Bonnet
Original : ''

Front Bumper
Original : ''

Back Bumper
Original : ''

Right Front Bumper
Original : ''

Left Front Bumper

Original : ''

Right Back Bumper
Original : ''

Left Back Bumper
Original : ''

Right Front Panel
Original : ''

Left Front Panel
Original : ''

Right Back Panel
Original : ''

Left Back Panel
Original : ''

Description

GCC 2020 KIA TELLURIDE EX | 3.8L V6

LIGHTS -PASSED

BODY -PASSED

CHASIS -PASSED

PAINT -DENTS ON RIGHT REAR DOOR

ROOF -PASSED

BONNET AND TRUNK PASSED

FENDERS - PASSED

BUMPERS -PASSED

RIMS

-PASSED

ENGINE

-PASSED

GEARBOX -PASSED

ALIGNMENT -PASSED

TIRES & BRAKES -PASSED

EXHAUST -PASSED

HISTORY: - ONE OWNER - 2 KEYS - SERVICE HISTORY PARTLY AVAILABLE - NO ACCIDENTS ON MOI SYSTEM

2020
Kia Telluride EX
3.8L V6
291 BHP

GCC Specs
108,486 kms

TERMS & CONDITIONS: This certificate shows the test values at the time of inspection only, Price Of Car is not responsible for any hidden or future defects as inspection was done according to Price Of Car standards.